



Form Name: **SST Best Practice Submission**

Completed on: **Tue Jan 09 20:10:46 UTC 2018**

---

## **Responses**

### **Submitter Name (optional)**

Mario Guzman

---

### **Submission Date**

January 9, 2018

---

### **Basis For Submission**

Best Practice - Positive Observation

---

### **Work Area**

Facility Wide / General

---

### **Other**

*No Response*

---

### **Severity Potential**

4 - Single Fatality

---

### **Work Category**

Both

---

### **Work Activity**

Other

---

## Other

Mobile Equipment Maintenance

---

## Hazard to be mitigated

Line of Fire

---

## Incident Brief

Contractor Vendor mechanic was positioned underneath the front end of the Bobcat, the forklift was running without an operator in the seat, and the mechanic failed to install the safety pin on the Bobcat cab which would prevent the top side from dropping down.

---

## Details

Nearby Contractor Lunch Tent

---

## Lesson Learned / Best Practice

Strengthening contractor vendor oversight requirements and to ensure that vendors understand the site policies and procedures. Also, to provide escorting while onsite to ensure they have the proper tools, controls, and are engaged in the site JSA process.

---

## Pictures or supporting documents

IMG\_1114.PNG

---

## For SST Vetting Team Use Only

---

### Review Date

January 9, 2018

---

### Submission Accepted (meets criteria)

N/A

---

### Classification

N/A

---

**Reviewer Name**

*No Response*

---

**Reviewer Recommendation**

*No Response*

---

**For SST Best Practices Governance**

---

**Communication Plan**

*No Response*

---

**Responsible person**

*No Response*

---

**Upload final BP Communication**

*No Response*

---