



Form Name: **SST Best Practice Submission**

Completed on: **Tue Jan 09 19:42:58 UTC 2018**

Responses

Submitter Name (optional)

Mario Guzman

Submission Date

January 9, 2018

Basis For Submission

Best Practice - Positive Observation

Work Area

Facility Wide / General

Other

No Response

Severity Potential

2 - Moderate Hurt (Weeks-Months)

Work Category

Both

Work Activity

Material Handling

Other

No Response

Hazard to be mitigated

Minimal Hazard or Injury Potential (Best Practice - must be safety related)

Incident Brief

While unloading scaffold material from a scafflod rack the employees noticed that a 4ft scaffold runner had pre-existing damaged.

Details

Unit 1 area, the scaffold runner had a hole burned through, and compromising the intergrity of the scaffold componet

Lesson Learned / Best Practice

When equipment arrives their should be a competent person to assist the recieveing department. This is to ensure that the equipment recieved is correct, there is no physical damage before it is accepted, and taken to the field.

Pictures or supporting documents

No Response

For SST Vetting Team Use Only

Review Date

January 9, 2018

Submission Accepted (meets criteria)

N/A

Classification

N/A

Reviewer Name

No Response

Reviewer Recommendation

No Response

For SST Best Practices Governance

Communication Plan

Communicated at project Weekly Safety Meeting, Weekly contractor Construction Meeting, the contractor communicated to the crafty in Daily Safety Radio Announcement, and JSA meetings.

Responsible person

No Response

Upload final BP Communication

No Response
